STELLA Deficiencies:

- We like to request for “SET PARAMETERS REPORT” of all components in STELLA.
- TELEPHONE SIGNAL IS NOT SHOWING ON THE ALARM COLUMNS WHEN MCR PHONE IS RINGING, This was available under SALMA.
- WHEN STARTING DG #3, “DG #3 CONTROL VOLTAGE FAILURE” ALARM CAME AND CHANGE THE DG #3 CONTROL FROM ‘AUTO’ TO ‘MANUAL’ (Observed during synchronizing of D/G #3 on 19th Oct 2020)
- Would like clarification of all the Alarms below:

Ack	State	EventTime	ObjectName	ObjectDescription	Message	Class	Cond
☒	ACT	2020/10/18 - 00:34:50	104 X161A		PMS (0000) Underflow	9950	HWError
☒	ACT	2020/10/16 - 08:31:20	204 X261A		PMS (0000) Underflow	9950	HWError
☒	ACT	2020/10/12 - 12:57:02	101 X461A		Cont14~_ACS880 (0000) Underflow	9950	HWError
☒	ACT	2020/10/06 - 01:53:07	DCU13_PM862	PM862 CPU	CPU Warning	9950	AlarmWarn
☒	ACT	2020/10/04 - 10:41:44	11		Cont14~_ACS880 (0000) RPA, RPB	9950	HWError
☒	ACT	2020/10/04 - 10:41:42	102 X371A		Cont01~CS6000M (0000) Channel error, I/O warning	9950	HWError
☒	ACT	2020/10/03 - 06:24:30	SWITCH_PN2_SW2_F	PN2 SW2 SWITCH FAULT	Signal difference	9950	AlarmDIFF
☒	ACT	2020/10/02 - 02:35:03	SWITCH_PN1_SW2_F	PN1 SW2 SWITCH FAULT	Signal difference	9950	AlarmDIFF
☒	ACT	2020/08/21 - 07:42:11	11		Cont01~CS6000M (0000) RPA, RPB	9950	HWError
☒	ACT	2020/01/02 - 11:15:33	DCU14_PM862	PM862 CPU	CPU Warning	9950	AlarmWarn
☒	ACT	2019/11/07 - 05:34:58	109 X155A		AS11 (0000) Channel error, I/O warning	9950	HWError
☒	ACT	2019/11/03 - 00:21:23	DCU11_PM862	PM862 CPU	CPU Warning	9950	AlarmWarn
☒	ACT	2019/11/03 - 00:21:20	DCU12_PM862	PM862 CPU	CPU Warning	9950	AlarmWarn
☒	ACT	2019/11/02 - 00:40:14	11 AS11	AS11 - ModuleBus	AS11 (0000) RPA, RPB	9950	HWError
☒	ACT	2019/10/18 - 06:37:28	ModuleBus	PMS - ModuleBus	PMS (0000) RPA, RPB	9950	HWError
☒	ACT	2019/10/11 - 03:01:44	208		AS21 (0000) Underflow	9950	HWError
☒	ACT	2019/10/11 - 03:01:42	105 X161B		PMS (0000) Underflow	9950	HWError
☒	ACT	2019/10/11 - 03:01:42	205 X261B		PMS (0000) Underflow	9950	HWError
☒	ACT	2019/10/11 - 03:01:40	11		Cont02~CS6000M (0000) RPA, RPB	9950	HWError
☒	ACT	2019/09/28 - 00:40:23	11	AS21 - ModuleBus	AS21 (0000) RPA, RPB	9950	HWError